

CC	HC	Road			Community Council						TEC Services					Signoff	
Ref	Ref	No.	Starts	Ends	Issue	Description of fault	Date reported	Photographs	Priority	Latest Date - Comment	Response	Priority	Date work scheduled	Date complete	Latest Date - Comment	TEC	CC
1		Unclassified - The main Braeintra road i.e. From the A890 down through Braeintra	Just uphill from Soluis mu Thuath	At the bridge across the burn	Water floods the road and freezes	Ditches and gullies under driveways are blocked uphill from Soluis mu Thuath causing water to run onto the road. In addition the drain hole on the bridge is blocked leaving a large amount of water in a pool on the road.	2010	Sent to George 23 May 2012	1	23 May 2012 - Potentially lethal when temperatures drop below zero 7th April 2013 -	Sandy MacVarish met with Mrs Arcscott to discuss the water problem. As a result of financial restraints there are no plans at present to carry out any major works within the area. It is hoped that some minor works could be carried out to alleviate some of the issues		No dates yet				
										7th April 2013 - The work done by TEC services has improved the the drainage at the bridge and this is no longer a problem. However there is still a slight problem with water running down the road rather than draining away to the verges, will check with Sandy what else can be done							
2	434898	Unclassified - The coast road that runs from Plockton through Duncraig and Craig to Achmore	Traveling from Plockton to Achmore, where the new tarmac surface starts after turning left at the T junction for Duncraig	Approximately 200 yards from the start of the new tarmac just past the third passing place	If cars leave the tarmac they will get stuck as they will be grounded on their chasis. This is particularly a problem if reversing to allow another car to pass in the dark	Where the new tarmac has been laid there is a drop of up to 330 mm to the verge in places	03/10/2012	I think it is fairly clear where the problem is, but let me know if you would like to to take some pictures to help identify the location		3 October 2012 - Reported by Phil Game not life threatening but would cause a major problem if someone did become stuck	Work is programmed to fill the edge drops with a suitable material which will taken up to road level thereby minimising the risk of vehicles grounding. It is hoped that these works will be carried out during the winter months.						
										7th April 2013 - Most of the verges have now been filled, but the few remaining ones need extensive work to form drains. Work will recommence when budgets permit.							
3	554969	Unclassified - The main Braeintra road i.e. From the A890 down through Braeintra	A few hundred metres from the T junction to the Achmore Plockton Road	At the T junction to the Achmore Plockton Road	Dangerous potholes deep enough to damage car suspensions.	More potholes than tarmac on this section of road.	19/03/2013	I think it is fairly clear where the problem is, but let me know if you would like to to take some pictures to help identify the location	2	07 April 2013 - Added to spreadsheet. May already be completed, will check with Sandy if any work is outstanding							